

Response to TN 039 - Location of Sensitive Receptors (Tabled Document 537)

Sensitive Receptor Locations from MFG Submission 813 (map on page 478) compared to Sensitive Receptor Locations in the Fingerboards Project EES (page 8-107)

(Note: In the EES, please refer to Table 8.33 (page 8-107) which lists the 49 sensitive receptors up to 3km from the project area boundary with their “R” ID number. Their corresponding sensitive receptor ID numbers are depicted on a map on the preceding page in the EES at Fig 8.25).

The rows shown in orange below do not have a corresponding Kalbar identified sensitive receptor ID number as published in the EES. Therefore, as stated in submission 813, only 60% of the sensitive receptor locations were identified in the EES.

MFG (813) sensitive receptor numbers (p 478)	Kalbar comments	Kalbar EES sensitive receptor numbers (p 8-107)	MFG comments
1		R48	
2	There are 2 structures on this property (within a single parcel) in close proximity, treated as a single receptor – R18		There is a separate residence which has a different address to R18 and therefore is a separate sensitive receptor. This sensitive receptor was not identified in the EES.
3		R18	
4			Someone living in shearing shed. This sensitive receptor was not identified in the EES.
5	There are two structures on this property (within a single parcel) in close proximity)		Two separately rated properties – have been subdivided with a residence on each. This sensitive receptor was not identified in the EES.
6			Two separately rated properties – have been subdivided with a residence on each. This sensitive receptor was not identified in the EES.
7		R17	
8		R01	
9		R02	
10		R03	
11		R04	
12			This sensitive receptor was not identified in the EES.
13		R05	
14		R06	
15		R25	
16		R08	
17		R09	
18			This sensitive receptor was not identified in the EES.
		R36	There is no residence here it was demolished so this receptor is technically void
19		R13	

20		R10	
21	paddock	R12	There is a residence here
22		R11	
23	Paddock (appears to be a landlocked)		There is a residence here. This sensitive receptor was not identified in the EES.
24			
25		R44	
26	Paddock		Significant sized house and shedding on hill. This sensitive receptor was not identified in the EES.
		R37	There is no residence here it was demolished so this receptor is technically void
27			This sensitive receptor was not identified in the EES.
28		R38	
29			This sensitive receptor was not identified in the EES.
30			This sensitive receptor was not identified in the EES.
31			This sensitive receptor was not identified in the EES.
32			This sensitive receptor was not identified in the EES.
33			This sensitive receptor was not identified in the EES.
34		R16	
35		R15	
36		R21	
37		R26	
38		R20	
39		R35	
40		R27	
41			This sensitive receptor was not identified in the EES.
42			This sensitive receptor was not identified in the EES.
43	No structure in this location		There is a residence here. This sensitive receptor was not identified in the EES.
44		R07	
45		R43	
46	No structure in this location		There is a residence here. This sensitive receptor was not identified in the EES.
47		R46	
48		R40	
49		R41	
50			This sensitive receptor was not identified in the EES.
51		R39	
52		R42	
53			This sensitive receptor was not identified in the EES.
54			This sensitive receptor was not identified in the EES.

55			This sensitive receptor was not identified in the EES.
56			This sensitive receptor was not identified in the EES.
57			This sensitive receptor was not identified in the EES.
58		R29	
59		R28	
60		R30	
61		R47	
62			This sensitive receptor was not identified in the EES.
63		R34	
64		R33	
65		R24	
66		R23	
67		R32	
68		R31	
69		R44	
70		R49	
71		R22	
72		R19	
73		R45	
74	A no. 74 cannot be located on the map		It is on the map and there is a residence (located beside 75 on our map). This sensitive receptor was not identified in the EES.
75			This sensitive receptor was not identified in the EES.
76			This sensitive receptor was not identified in the EES.
77			This sensitive receptor was not identified in the EES.
78			Someone lives in the shearing shed. This sensitive receptor was not identified in the EES.
79			This sensitive receptor was not identified in the EES.
80	A no. 80 cannot be located on the map		Apologies number fell off, it is located north of R27 so not on the EES map. This sensitive receptor was not identified in the EES.
81	Farm dam		There is a residence here. This sensitive receptor was not identified in the EES.
82	This location is a paddock		There is a residence here. This sensitive receptor was not identified in the EES.
Total	82	49 *	*R36 & R37 no longer have residences so the total identified in EES is technically 47