

les basic

spire—care & maintenance

metal—powdercoated, polished

wipe surface with a soft, moist cloth. If you must use detergent, use a neutral diluted detergent. Dry the surface with a clean, soft cloth after washing. Avoid bleaches, acids, or abrasive materials.