

# les basic

## nepal — care & maintenance

### **metal — powdercoated, polished**

wipe surface with a soft, moist cloth. If you must use detergent, use a neutral diluted detergent. Dry the surface with a clean, soft cloth after washing. Avoid bleaches, acids, or abrasive materials.