## les basic

## valet - care & maintenance

avoid leaving the product in direct sunlight for prolonged peroids of time.

## timber-solid, veneer

wipe surface with a soft, moist cloth. If you must use detergent, use a neutral diluted detergent. Dry the surface with a clean, soft cloth after washing. Avoid bleaches, acids, or abrasive materials.

## metal-powdercoated, polished

wipe surface with a soft, moist cloth. If you must use detergent, use a neutral diluted detergent. Dry the surface with a clean, soft cloth after washing. Avoid bleaches, acids, or abrasive materials.

valet—care & maintenance www.lesbasic.com