


Ground Vibration Report

Summary

Event Type	Seismic Event
Magnitude	0.8
Event Date	2026/03/05
Event Time	01:11:35 Australia/Melbourne
Location	Phoenix 3695 RAW
Distance Below Surface	~1450 m
Notes	-



PPV Measurements

Site ID	X Component		Y Component		Z Component		Vector
	PPV (mm/s)	Freq (Hz)	PPV (mm/s)	Freq (Hz)	PPV (mm/s)	Freq (Hz)	
FGV2	< 0.20	31.5	0.21	43.0	< 0.20	80.1	0.28
FGV4	< 0.20	16.4	< 0.20	79.7	< 0.20	33.9	< 0.20
FGV16	< 0.20	18.7	< 0.20	17.1	< 0.20	34.6	< 0.20
FGV7	< 0.20	18.4	< 0.20	17.4	< 0.20	18.6	< 0.20
FGV5	< 0.20	23.2	< 0.20	22.8	< 0.20	26.2	< 0.20
FGV1	< 0.20	16.3	< 0.20	23.5	< 0.20	31.3	< 0.20
FGV3	< 0.20	18.1	< 0.20	16.9	< 0.20	20.6	< 0.20
FGV11	< 0.20	33.5	< 0.20	25.8	< 0.20	29.5	< 0.20
FGV14	< 0.20	29.4	< 0.20	31.8	< 0.20	36.4	< 0.20
FGV6	-	-	-	-	-	-	-
FGV8	-	-	-	-	-	-	-
FGV9	-	-	-	-	-	-	-
FGV10	-	-	-	-	-	-	-
FGV12	-	-	-	-	-	-	-
FGV13	-	-	-	-	-	-	-
FGV15	-	-	-	-	-	-	-
FGV17	-	-	-	-	-	-	-
FGV18	-	-	-	-	-	-	-
FGV19	-	-	-	-	-	-	-
FGV20	-	-	-	-	-	-	-
FGV21	-	-	-	-	-	-	-
FGV22	-	-	-	-	-	-	-
FGV23	-	-	-	-	-	-	-
FGV24	-	-	-	-	-	-	-
FGV25	-	-	-	-	-	-	-

Per-component Peak Particle Velocities (PPV) vs. Zero Crossing Frequencies.
Line indicates cosmetic damage guidelines
(residential buildings, Fig. J4.4.2.1, AS 2187.2:2006).

Legend: Below detection threshold Below 15 mm/s Above 15 mm/s Above damage curve

