


Ground Vibration Report

Summary

|                        |                              |
|------------------------|------------------------------|
| Event Type             | Seismic Event                |
| Magnitude              | 1.5                          |
| Event Date             | 2026/05/07                   |
| Event Time             | 21:54:35 Australia/Melbourne |
| Location               | Phoenix 3925 RAW             |
| Distance Below Surface | ~1240 m                      |
| Notes                  | -                            |



PPV Measurements

| Site ID | X Component |           | Y Component |           | Z Component |           | Vector |
|---------|-------------|-----------|-------------|-----------|-------------|-----------|--------|
|         | PPV (mm/s)  | Freq (Hz) | PPV (mm/s)  | Freq (Hz) | PPV (mm/s)  | Freq (Hz) |        |
| FGV2    | 0.42        | 65        | 0.43        | 17.9      | 0.26        | 31.7      | 0.44   |
| FGV4    | 0.27        | 65.1      | 0.29        | 82.4      | 0.24        | 32.7      | 0.42   |
| FGV1    | 0.40        | 24.7      | 0.33        | 25.2      | 0.20        | 40.3      | 0.41   |
| FGV11   | 0.28        | 28.6      | 0.34        | 31.2      | 0.22        | 29.3      | 0.39   |
| FGV14   | 0.27        | 27.5      | 0.29        | 34.2      | < 0.20      | 39.5      | 0.36   |
| FGV10   | < 0.20      | 33.2      | 0.34        | 24.1      | < 0.20      | 24.8      | 0.35   |
| FGV3    | < 0.20      | 19.8      | < 0.20      | 20.2      | 0.32        | 25.3      | 0.33   |
| FGV7    | 0.26        | 25.2      | < 0.20      | 13.0      | < 0.20      | 21.8      | 0.30   |
| FGV5    | < 0.20      | 25.1      | 0.26        | 27.5      | < 0.20      | 29.1      | 0.28   |
| FGV16   | 0.22        | 25.9      | < 0.20      | 16.1      | < 0.20      | 29.1      | 0.25   |
| FGV20   | < 0.20      | 11.4      | < 0.20      | 15.1      | < 0.20      | 11.4      | < 0.20 |
| FGV18   | < 0.20      | 18.4      | < 0.20      | 15.7      | < 0.20      | 17.9      | < 0.20 |
| FGV15   | < 0.20      | 14.5      | < 0.20      | 21.2      | < 0.20      | 12.5      | < 0.20 |
| FGV6    | < 0.20      | 18.1      | < 0.20      | 23.9      | < 0.20      | 33.2      | < 0.20 |
| FGV17   | < 0.20      | 16.5      | < 0.20      | 18.0      | < 0.20      | 25.7      | < 0.20 |
| FGV8    | -           | -         | -           | -         | -           | -         | -      |
| FGV9    | -           | -         | -           | -         | -           | -         | -      |
| FGV12   | -           | -         | -           | -         | -           | -         | -      |
| FGV13   | -           | -         | -           | -         | -           | -         | -      |
| FGV19   | -           | -         | -           | -         | -           | -         | -      |
| FGV21   | -           | -         | -           | -         | -           | -         | -      |
| FGV22   | -           | -         | -           | -         | -           | -         | -      |
| FGV23   | -           | -         | -           | -         | -           | -         | -      |
| FGV24   | -           | -         | -           | -         | -           | -         | -      |
| FGV25   | -           | -         | -           | -         | -           | -         | -      |

Per-component Peak Particle Velocities (PPV) vs. Zero Crossing Frequencies.  
Line indicates cosmetic damage guidelines  
(residential buildings, Fig. J4.4.2.1, AS 2187.2:2006).

Legend: Below detection threshold Below 15 mm/s Above 15 mm/s Above damage curve

