


Ground Vibration Report

Summary

|                        |                              |
|------------------------|------------------------------|
| Event Type             | Seismic Event                |
| Magnitude              | 1.4                          |
| Event Date             | 2026/05/14                   |
| Event Time             | 08:46:56 Australia/Melbourne |
| Location               | Phoenix 3890 SACC            |
| Distance Below Surface | ~1320 m                      |
| Notes                  | -                            |



PPV Measurements

| Site ID | X Component |           | Y Component |           | Z Component |           | Vector |
|---------|-------------|-----------|-------------|-----------|-------------|-----------|--------|
|         | PPV (mm/s)  | Freq (Hz) | PPV (mm/s)  | Freq (Hz) | PPV (mm/s)  | Freq (Hz) |        |
| FGV2    | 1.11        | 49.5      | 0.73        | 41.9      | 0.43        | 42.7      | 1.19   |
| FGV5    | 0.42        | 18.5      | 0.66        | 24.3      | 0.21        | 31.4      | 0.70   |
| FGV11   | 0.47        | 30        | 0.58        | 29.6      | 0.31        | 32.4      | 0.65   |
| FGV1    | 0.59        | 21.9      | 0.48        | 23.6      | 0.28        | 31.2      | 0.61   |
| FGV7    | 0.40        | 26.6      | 0.44        | 18.5      | 0.29        | 22.0      | 0.47   |
| FGV10   | < 0.20      | 29.6      | 0.41        | 23.1      | < 0.20      | 19.8      | 0.41   |
| FGV16   | 0.40        | 24.8      | 0.20        | 11.4      | 0.32        | 34.7      | 0.41   |
| FGV3    | 0.20        | 40.4      | < 0.20      | 32.3      | 0.29        | 26.6      | 0.29   |
| FGV18   | 0.20        | 16.1      | 0.24        | 16.1      | < 0.20      | 21.0      | 0.27   |
| FGV6    | < 0.20      | 32.3      | 0.22        | 33.5      | < 0.20      | 27.1      | 0.26   |
| FGV4    | < 0.20      | 33.3      | 0.26        | 18.1      | < 0.20      | 35.7      | 0.26   |
| FGV15   | 0.20        | 14        | < 0.20      | 15.5      | < 0.20      | 12.7      | 0.23   |
| FGV20   | < 0.20      | 17.5      | < 0.20      | 15.7      | < 0.20      | 0.8       | < 0.20 |
| FGV14   | < 0.20      | 35.9      | < 0.20      | 31.5      | < 0.20      | 31.9      | < 0.20 |
| FGV9    | < 0.20      | 38.7      | < 0.20      | 33.9      | < 0.20      | 50.9      | < 0.20 |
| FGV17   | < 0.20      | 17        | < 0.20      | 15.0      | < 0.20      | 20.5      | < 0.20 |
| FGV13   | < 0.20      | 16.9      | < 0.20      | 18.8      | < 0.20      | 23.0      | < 0.20 |
| FGV24   | < 0.20      | 7.7       | < 0.20      | 8.6       | < 0.20      | 10.3      | < 0.20 |
| FGV8    | -           | -         | -           | -         | -           | -         | -      |
| FGV12   | -           | -         | -           | -         | -           | -         | -      |
| FGV19   | -           | -         | -           | -         | -           | -         | -      |
| FGV21   | -           | -         | -           | -         | -           | -         | -      |
| FGV22   | -           | -         | -           | -         | -           | -         | -      |
| FGV23   | -           | -         | -           | -         | -           | -         | -      |
| FGV25   | -           | -         | -           | -         | -           | -         | -      |

Per-component Peak Particle Velocities (PPV) vs. Zero Crossing Frequencies. Line indicates cosmetic damage guidelines (residential buildings, Fig. J4.4.2.1, AS 2187.2:2006).

Legend: Below detection threshold Below 15 mm/s Above 15 mm/s Above damage curve

