


Ground Vibration Report

Summary

Event Type	Seismic Event
Magnitude	1.0
Event Date	2026/06/18
Event Time	18:29:52 Australia/Melbourne
Location	Phoenix 3690 ACC
Distance Below Surface	~1480 m
Notes	-



PPV Measurements

Site ID	X Component		Y Component		Z Component		Vector
	PPV (mm/s)	Freq (Hz)	PPV (mm/s)	Freq (Hz)	PPV (mm/s)	Freq (Hz)	
FGV2	0.23	40.5	< 0.20	40.0	< 0.20	71.9	0.25
FGV4	< 0.20	83.7	< 0.20	91.4	< 0.20	84.4	< 0.20
FGV5	< 0.20	27.6	< 0.20	27.8	< 0.20	28.7	< 0.20
FGV10	< 0.20	37.2	< 0.20	18.9	< 0.20	53.8	< 0.20
FGV14	< 0.20	31.8	< 0.20	39.9	< 0.20	41.2	< 0.20
FGV15	< 0.20	22.8	< 0.20	20.3	< 0.20	25.7	< 0.20
FGV1	< 0.20	19.1	< 0.20	24.7	< 0.20	33.1	< 0.20
FGV3	-	-	-	-	-	-	-
FGV6	-	-	-	-	-	-	-
FGV7	-	-	-	-	-	-	-
FGV8	-	-	-	-	-	-	-
FGV9	-	-	-	-	-	-	-
FGV11	-	-	-	-	-	-	-
FGV12	-	-	-	-	-	-	-
FGV13	-	-	-	-	-	-	-
FGV16	-	-	-	-	-	-	-
FGV17	-	-	-	-	-	-	-
FGV18	-	-	-	-	-	-	-
FGV19	-	-	-	-	-	-	-
FGV20	-	-	-	-	-	-	-
FGV21	-	-	-	-	-	-	-
FGV22	-	-	-	-	-	-	-
FGV23	-	-	-	-	-	-	-
FGV24	-	-	-	-	-	-	-
FGV25	-	-	-	-	-	-	-

Per-component Peak Particle Velocities (PPV) vs. Zero Crossing Frequencies.
Line indicates cosmetic damage guidelines
(residential buildings, Fig. J4.4.2.1, AS 2187.2:2006).

Legend: Below detection threshold Below 15 mm/s Above 15 mm/s Above damage curve

