


Ground Vibration Report

Summary


Event Type	Seismic Event
Magnitude	0.7
Event Date	2026/07/05
Event Time	04:37:26 Australia/Melbourne
Location	Phoenix 3690 ACC
Distance Below Surface	~1470 m
Notes	-



PPV Measurements

Site ID	X Component		Y Component		Z Component		Vector
	PPV (mm/s)	Freq (Hz)	PPV (mm/s)	Freq (Hz)	PPV (mm/s)	Freq (Hz)	
FGV2	< 0.20	45.2	< 0.20	62.4	< 0.20	72.6	0.22
FGV4	< 0.20	93.9	< 0.20	101.2	< 0.20	97.6	< 0.20
FGV6	< 0.20	66.8	< 0.20	64.1	< 0.20	59.6	< 0.20
FGV7	< 0.20	24.7	< 0.20	28.2	< 0.20	34.7	< 0.20
FGV1	-	-	-	-	-	-	-
FGV3	-	-	-	-	-	-	-
FGV5	-	-	-	-	-	-	-
FGV8	-	-	-	-	-	-	-
FGV9	-	-	-	-	-	-	-
FGV10	-	-	-	-	-	-	-
FGV11	-	-	-	-	-	-	-
FGV12	-	-	-	-	-	-	-
FGV13	-	-	-	-	-	-	-
FGV14	-	-	-	-	-	-	-
FGV15	-	-	-	-	-	-	-
FGV16	-	-	-	-	-	-	-
FGV17	-	-	-	-	-	-	-
FGV18	-	-	-	-	-	-	-
FGV19	-	-	-	-	-	-	-
FGV20	-	-	-	-	-	-	-
FGV21	-	-	-	-	-	-	-
FGV22	-	-	-	-	-	-	-
FGV23	-	-	-	-	-	-	-
FGV24	-	-	-	-	-	-	-
FGV25	-	-	-	-	-	-	-

Per-component Peak Particle Velocities (PPV) vs. Zero Crossing Frequencies.
Line indicates cosmetic damage guidelines
(residential buildings, Fig. J4.4.2.1, AS 2187.2:2006).



Legend:  Below detection threshold  Below 15 mm/s  Above 15 mm/s  Above damage curve

